

Town of Fremont Building Inspectors Office

Building Official - Thom Roy Building Inspector Hours

3:30 PM - 4:30 PM

Wed Evenings 5:00 PM - 7:00 PM

Field: Mon - Thurs 10:30 AM - 3:30 PM

-and by appointment -

Table Information Supportive of ICC Climatic and Geographic Criteria

TABLE R301.2 (1) IRC

Ground Snow Load 50

Wind - Speed (mph) 50 yr mean 90- 100 mph

Seismic Design Criteria C

*site specific soil profiles and site specific usage may impact design criteria

Frost Line Depth (<u>footing depth minimum</u>) 4 foot

Weathering - grade of masonry to be determined from this value

Severe

Ice Shield under-layment required: YES

Air-Freezing Index Zone 15

Winter, Design dry bulb*

Concord – January -15 degrees

Summer, Design dry-bulb

Concord – July +90 degrees

Degrees day heating Epping 6884 Zone 15 – degree days 7,000 – 8499

*NOAA "Annual Degree Days – 1971-2000

Outdoor Design Dry-bulb temperature at 97 1/2 % values for winter

Concord -3 degrees IBC Mapping 0 degrees

Average Mean Temperature

Durham Concord 47 degrees 45.3 degrees

Termite Infestation Probability Mapping Slight to Moderate

Decay Probability Mapping Slight to Moderate

Flood Hazard - National Flood Insurance Program

Flood Plain Development Ordinance -

Article X of Fremont Zoning Ordinance - Adopted 1993

Flood Hazard Mapping

FIRM - Dated June 19, 1989 and as revised May 17, 2005

This information was compiled for specific purposes as an advisory check sheet and its use and interpretation otherwise is not intended - Thomas Roy – Building Inspector

Revised 02-07-2006